

Surface mount dropper resistor



PCB pad is provided for mounting chip resistor.



Create gap in copper with file or saw and glue in place where resistor is required.



Remove chip resistor from card and plastic container Solder chip resistor to PCB at each end



Solder wires to each end of the chip resistor or PCB.

http://www.geocities.com/nigellawton009